TRANSP National Transportation Safety Board	NTS	SB ID:	OPS10IA090	A	Aircraft Regist	Aircraft Registration Number:				
FACTUAL REPORT	Occ	currence	e Date: 04/19)/2010	Most Critical Ir	Most Critical Injury: None				
AVIATION	AVIATION Crybon Occurrent				Irrence Type: Incident Investigated By: N					
Location/Time						-				
Nearest City/Place	State	Zip	Code	Local Time	Time Zone	Time Zone				
Burbank	CA	`			PDT					
Airport Proximity: On Airport/Airstrip	Distance F	rom La	nding Facility:	0						
Aircraft Information Summary										
Aircraft Manufacturer			Model/Series	3			Type of Aircraft			
BOEING			737-7H4				Airplane			
Revenue Sightseeing Flight: No			Air N	ledical Transpo	ort Flight: No					
Narrative										
Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident: *** Note: NTSB investigators used data provided by various sources and may not have traveled in support of this investigation to prepare this aircraft incident report. ***										
On Monday, April 19, 2010 at approximately 1058 pacific daylight time, Southwest Air Lines (SWA) flight 649, a Boeing 737-700 and N4415R, a Cessna 172 were involved in a near collision on the surface at the Bob Hope Airport (BUR), Burbank, California. The B737 was landing on runway 8, and the C172 was in the departure phase of a touch and go on runway 15, when it passed airborne through the intersection in front of the B737 flight. The incident occurred during daytime visual meteorological conditions (VMC).										
The B737 was on a regularly scheduled passenger flight from Metropolitan Oakland International Airport (OAK), Oakland, California enroute to BUR and was operating under the provisions of 14 Code of Federal Air Regulation Part 121. The Southwest flight had 119 passengers and a crew of five onboard. No injuries were reported.										
The C172 was practicing take-of Code of Federal Regulations Par										
go approaches in the traffic pa instructed by ATC to enter a le minutes later, the B737 reporter landing system (ILS) approach t clearance to runway 8, and then Immediately following those clear	At approximately 1046, N4415R reported in to BUR air traffic control tower (ATCT) requesting touch and go approaches in the traffic pattern. The C172 completed one touch and go to runway 8 and was then instructed by ATC to enter a left downwind for runway 15 for his second approach. Approximately two minutes later, the B737 reported in to BUR ATCT on approximately an 8-mile final for an instrument landing system (ILS) approach to runway 8. The local controller (LC) issued the B737 a landing clearance to runway 8, and then subsequently issued the C172 a touch and go clearance to runway 15. Immediately following those clearances, the LC became moderately busy providing traffic advisories to other aircraft in the airspace; however, the B737 and C172 were not provided traffic advisories on each other.									
Approximately two minutes later, the C172 was airborne in the departure phase of a touch and go on runway 15 and passed through the intersection of runway 15/8 in front of the B737 landing on runway 8.										
According to the LC and the controller in charge (CIC), they did not see the situation develop between the C172 and B737, because another aircraft that had just departed distracted them, and their attention was focused on the radar display, not out the tower window. The LC and CIC first became aware of the situation when the clearance delivery/flight data controller (CD/FD) looked out of the window and saw said "hey!" when he saw the C172 airborne and climbing over the intersection, and the landing B737 flight rolling through the same intersection, perpendicular to each other. The B737 continued to his gate, and C172 completed two more approaches at BUR before departing toward Van Nuys.							and their IC first became boked out of the rsection, and the her. The B737			
	FAC	TUAL	REPORT - A	VIATION			Page 1			

	This space for binding	
National Transportation Safety Board	NTSB ID: OPS10IA090A	
FACTUAL REPORT	Occurrence Date: 04/19/2010	
AVIATION ETYBON	Occurrence Type: Incident	
Narrative (Continued)		
Burbank airport had several video c operations. One of those cameras c approximately 10 seconds had lapsed had rolled through that same inters Updated on Dec 27 2011 8:49AM	aptured the incident. The repla from the time C172 passed over	y of the video indicated that

FACTUAL REPORT - AVIATION

National Transportation Safety Board	NTS	NTSB ID: OPS10IA090A									
FACTUAL REPORT	Occ	urrenc	e Date:	04/19/2010							
AVIATION	Occ	urrenc	е Туре	: Incident							
Landing Facility/Approach Information						L					
Airport Name Air			Airport ID: Airport Elevation Runway Used Runway						y Length Runway Width		
Bob Hope Airport K			JR	778 Ft. MSL	L 08		5802		15	0	
Runway Surface Type: Asphalt							<u>. </u>				
Runway Surface Condition: Dry											
Approach/Arrival Flown:											
VFR Approach/Landing:											
Aircraft Information											
Aircraft Manufacturer BOEING			Model/ 737-7					Serial 33832	ll Number 32		
Airworthiness Certificate(s):											
Landing Gear Type:											
Amateur Built Acft? No Number of	Seats: 140			d Max Gross Wt.			LBS	Numbe	er of Engine	»s: 2	
Engine Type: Turbo Fan			gine Ma FM INT	nufacturer: L.		Model/Ser CFM56					
- Aircraft Inspection Information								—			
Type of Last Inspection Da) of Last	t Inspection	Time Si	ince Last Inspe		ours	Airframe T	otal Time Hours	
- Emergency Locator Transmitter (ELT) Informa	ation	1			<u> </u>						
ELT Installed?/Type		ELT Operated? ELT Aided in Locating Accident Site?						ent Site?	?		
Owner/Operator Information											
Registered Aircraft Owner			Street A	Address 2702 LOVE F		 \D					
			City			<u>N</u>			State	Zip Code	
		+		DALLAS					ТХ	75235-1908	
Operator of Aircraft			Street A	ddress 2702 LOVE F	FIELD D)R					
			City	State	Zip Code						
DALLAS TX 75 Operator Does Business As: Operator Designator Code: SWAA							75235-1908				
- Type of U.S. Certificate(s) Held:					`	po.a.o		/			
Air Carrier Operating Certificate(s): Flag Carrie	er/Domestic										
Operating Certificate:				Operator Certifi	icate:						
Regulation Flight Conducted Under:											
Type of Flight Operation Conducted: Schedule	ed; Domestic	; Pas	senger	Only							
	FACT	UAL	REPO	RT - AVIATION						Page 2	

Nation	TRANS	Safety Boar	d	NTSB ID: OPS10IA090A											
F	ACTUAL RI	EPORT			Occurrence Date: 04/19/2010										
	AVIATI ETYBO	~ ~		F	Occurrence Type: Incident										
Eirot Dilo						,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,									
First Pilot Information Name City						City					State	e C	ate of Birth	Age	
													_		
Sex: Seat Occupied: Occupational Pilot? Certificate Number:															
Certificate				Occu		101 ?					Cer	lincale	Numbe	÷I.	
Certificate	(3).														
Airplane R	ating(s):														
Rotorcraft/	Glider/LTA:														
Instrument	Rating(s):														
Instructor I	Rating(s):														
Current Bie	ennial Flight Revie	ew?													
Medical Ce	ert.:	Medic	al Cert. S	Status:						Date	of La	st Me	dical Ex	am:	
- Flight Tin	ne Matrix	All A/C	This Make and Model		Airplane ingle Engine	Airplane Mult-Engine		Night	Instrument Actual S		ulated	Rotorcraft		Glider	Lighter Than Air
Total Time)														
Pilot In Co	mmand(PIC)														
Instructor															
Instruction														_	
Last 90 Da Last 30 Da															
Last 24 Ho	-													-	
Seatbelt U		Sho	ulder Hari	ness U	Jsed?			Toxicology Performed? Second Pilot?							
Elight Pla	an/Itinerary														
	ght Plan Filed: U	nknown													
Departure								State		Airport Ide	entifie	r	Depart	ure Time	Time Zone
Oakland						СА			KOAK		1008		PDT		
Destination					State		Airport Ide	irport Identifier							
Same as Accident/Incident Location							KBUR								
Type of Cl	earance:														
Type of Ai	rspace: Air Tra	affic Contro	; Class (С											
Weather	Information														
Úặį đế ÁSou	urce of Wx Inform	ation:													
	Unkno	wn													

FACTUAL REPORT - AVIATION

Nationa	al Transportation Safety	Board	NTSB ID:	NTSB ID: OPS10IA090A								
	ACTUAL REPOI		Occurren	ce Date:	04/19/2	010		1				
	AVIATION		Occurren	Occurrence Type: Incident								
Weather	Information										_	
WOF ID	Observation Time	Time Zone	WOF Elevat	ion	WOF Di	stance From	Accio	dent Site		Direction From Accident Site		
KBUR	1053	PDT	Ft	. MSL				NM		Deg. Mag.		
Sky/Lowes	t Cloud Condition: Cle	ar				Ft. AG	L	Condition of Light: Day				
Lowest Ce	iling: None		Ft.	AGL	Visibi	lity:	10	SM	Alti	meter: "H	Чg	
Temperatu	ure: 20 °C	Dew Point:	9 °C	Weath	ner Condi	tions at Accie	dent S	Site: Visual	Conc	litions		
Wind Direc	ction: 130	Wind Spee	ed: 7		Wind	d Gusts:						
Visibility (F	RVR): Ft	. Visibility (I	RVV)	SM								
Precip and	l/or Obscuration:			I							_	
Accident	Information											
	mage: None		Aircraft Fir	e [.] None				Aircraft Exp	olosio	n None	—	
Allolation			Anoranti in						510310	in None	—	
laium (Cu		[Fatal (Daniaura Minu		Neze	TOTAL					—	
	mmary Matrix	Fatal	Serious Mino	or	None	TOTAL						
First Pi Second					1	1						
					1	1						
Studen		+ +										
	nstructor	+										
Check												
	Engineer											
	Attendants				3	3						
Other C		+										
Passer	<u> </u>	+			119							
	ABOARD -	↓			124	124						
Other C				_								
- GRANL	D TOTAL -				124	124						
L												
			FACTUAL	REPOI	RT - AV	IATION				Page 4		

National Transportation Safety Board	NTSB ID: OPS10IA090A	
National Transportation Safety Board FACTUAL REPORT	Occurrence Date: 04/19/2010	
AVIATION	Occurrence Type: Incident	
Administrative Information		
nvestigator-In-Charge (IIC)		
Betty Koschig		
Additional Persons Participating in This Accident/	Incident Investigation:	
Todd Luepker Federal Aviation Administration Washington, DC		
Leslie Jackson Federal Aviation Administration Washington, DC		
Seann Jordan National Air Traffic Controller Association Colorado Springs, CO		